



Proposed double check conflicts with roll up door for zamboni. Please advise on new location for double check.

Would double check work here? Is 20' enough for zamboni clearance?

